COMPLETION REPORT

1	Name of the work	Removal of debris and desilting of drains in Bagalagunte ward no. 14 Dasarahlli Sub Divison.
2	Sanctioned Estimate No. & Date	EE/AS/48/16-17. dt 30.12.2016 EE/TS/65/16-17. dt 30-12-2016.
3	Head of Account which is chargeable	1771.
4	Instrument Order NO. & Date	WO/133/16-17 date: 10/3/2017
5	Name Of Contractor	Sri. M. N. Ramaiah, #35/28, 6th Main, Dattatreya Nagara, BSK 3rd Stage, Bengaluru- 560085
6 a	Time Stipulated for Completion of work	30 days
b	Delay in Exculpation of Work	26 days.
7	Measurement recorded in	2404/14-15 pno 340398/2 to 340450/2
8	Check Measurement of the Asst	6/05/2017
9	Name of the office/official in charge of the work	—
10	a) Asst. Eng/junior Eng	D.S. ಮಂಜುನಾಥ
	b) Asst. Exe Engineer	ರಂಗಸ್ವಾಮಿ. ಕೆ.

Sanctioned Estimate Amout	Amout Claims As per Actually Vide As per bills	Excess	Savings
10.ಲಕ್ಷ	992199-00	—	7801-00

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER.

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

ASSIATANT EXECUTIVE ENGINEER